Hyderabad Cricket Association Rajiv Gandhi Internatiol Cricket Stadium, Uppal

Replace and repair of Main kitchen fresh air system and exaust duct BOQ - 04

Sl			tchen fresh air syst					Q - 04
No	Scope of work	Product details	Specifications	Make	Qty	UOM	Rate	Amount
	Supply and installation of Fresh air coders	Usage/Application	Industrial spaces, large cooling areas, Specialised cooling application		3	No's		
		Туре	Evaporator					
		Size	Medium	1				
		Material	Plastic	1 1				
1		Model Name/Number	BreezAir TBQ,TBS,TBS-i series	Breezair				
		Features	6500 CFM,1200 sq ft / cooler cooling capacity,Positive Pressure,Easy service					
		Power	1.5kW					
		Color	Grey/ ivory					
		Blower Fan	Axial					
		Blower Fan Diameter Mm Inch	21					
		Cellulose Pad Thickness		1 1				
		Inch	4					
2	Supply and installtion of 2.5 Sq mm 3 Core, copper cable and 6" galvized tray and fixing in tray			Havells/ Finolex or Polycab	150	Mtrs		
3	Supply and installation of inlet and outlet piping with 25 mm valves			Zoloto, Jagaur	3	Sets		
4	Supply and installtion of fresh air system control box with incoming and out going mcb's and contactors			L&T, Legrand, schneider	1	No		
5	Existing exaust duct cleaning				48	Mtrs		
6	Duct patch work 1 Mtr X 1 Mtrs				1	No		
/	Supply and replacement of to existing exaust duct Joint fabric				2	No's		
8	Repair and rewinding ot existing exaust duct 7.5 HP Motors				2	No		
			GST 18 %					
		q	Total Amount					

(SUNEEL KANTE)

Chief Executive Officer